

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**



1/19

121-00145A00C








FIG 1





3/19



Step (3)  
insert pole  
into sleeve

Step (4) - install handle/pin.

Step (1)

5F1

5G

5B1

5E 5F2



Step (6) : remove handle

5A



5

5B

FIG 2B1



5/19



6/19




FIG 2C1








FIG. 2C2



7/19







9/19




FIG 3A





FIG. 3B

11/19









FIG. 3C




13/19





14/19



15/19





FIG. 5




FIG. 6





FIG. 7B







FIG. 7A


17/19





18/19





3/19




FIG. 10

